


HAT PATCH MEASURING GUIDE

Not all patches will fit all cap styles. Please use these guidelines to ensure that your patch will fit properly.


STEP 1

Find the Curvature Break Line - the point where the top of the hat begins to curve. This is the maximum point for the top of the patch.



STEP 2

Find the Brim Line - the point where the brim meets the hat. There must be at least 1/2" distance between the brim line and your patch.



STEP 3

Measure the distance between the Brim Line and the Curvature Break Line. Subtract the Brim Line, then subtract 1/2" to find your maximum patch height.

